AMI BIOS Beep Codes:

Beeps	Error Message	Description
1 short	DRAM refresh failure	The programmable interrupt timer or programmable interrupt controller has probably failed
2 short	IVIAMORY DARITY ARROR	A memory parity error has occurred in the first 64K of RAM. The RAM IC is probably bad
3 short	Race 64K memory fallife	A memory failure has occurred in the first 64K of RAM. The RAM IC is probably bad
4 short	System timer failure	The system clock/timer IC has failed or there is a memory error in the first bank of memory
5 short	Processor error	The system CPU has failed
6 short		The keyboard controller IC has failed, which is not allowing Gate A20 to switch the processor to protected mode. Replace the keyboard controller
I/ CDOT		The CPU has generated an exception error because of a fault in the CPU or motherboard circuitry
8 short	Display memory read/write error	The system video adapter is missing or defective
9 short		The contents of the system BIOS ROM does not match the expected checksum value. The BIOS ROM is probably defective and should be replaced
IIII SHAFE	CMOS shutdown register read/ write error	The shutdown for the CMOS has failed
11 short	Cache error	The L2 cache is faulty
1 long, 2 short	Hallite in Video system	An error was encountered in the video BIOS ROM, or a horizontal retrace failure has been encountered
1 long, 3 short	Memory test failure	A fault has been detected in memory above 64KB
1 long, 8 short	Display test failure	The video adapter is either missing or defective
2 short	POST Failure	One of the hardware testa have failed
1 long	POST has passed all tests	